

# Model 541 Frequency Calibrator with Totalizer Operating Instructions

## A. Basic Keypad Operations

### ① EZ-Check™ Switch/EZ-Step™ Pushbutton

Slide the switch to select the user stored values for calibration points.  
Push the EZ-Step™ pushbutton like a stop Watch to Run or Stop Totalizing.

### ③ ON/OFF Button

Press **ON/OFF** to turn the Model 541 on or off.

### ④ MENU Button

Press and release the menu button and a mode of operation menu will appear with all the selections for operation mode.

**REFER TO SECTION B.**

### ⑤ READ/GATE TIME Button

Press and release **READ/GATE TIME** to change read modes. These are:

- Read Source CPH 1 – 20000
- Read CPM 0.1 – 2000.0
- Read HZ 0.01 – 200.00
- Read HZ 0.1 – 2000.0
- Read KHZ 0.001 – 20,000
- Totalizer

Press and hold **READ/GATE TIME** to select gate time adjustment for Source & Read Totalize mode.

**Then press the SOURCE/AMPLITUDE or STORE/CLEAR button to save selections and to exit.**

### ⑥ STORE/CLEAR Button


In source mode press the **STORE/CLEAR** to save the calibration values. The display will flash "STORED" to confirm.

In read mode press **STORE/CLEAR** to clear the values saved in the EZ-Check™ HI and LO positions. The display will flash "CLEARED" to confirm.

### ⑦ EZ-Dial™ Knob

**Source mode** -Turn the EZ-Dial™ knob to adjust the output level. Press and turn to adjust 100X faster.

**Read mode** – Turn the EZ-Dial™ knob to adjust the trigger level.



### ② SOURCE/AMPLITUDE Button

Press and release **SOURCE/AMPLITUDE** to change source modes. These are:

- Source CPH 1 - 20000
- Source CPM 0.1 – 2000.0
- Source HZ 0.01 – 200.00
- Source HZ 0.1 – 2000.0
- Source KHZ 0.001 – 20,000
- Totalizer

Press and hold **SOURCE/AMPLITUDE** to change amplitude voltage from 0.1-12Vp.

**Then press the SOURCE/AMPLITUDE or STORE/CLEAR button to save selections and to exit.**





# Model 541 Operating Instructions

## B. Model 541 Configuration

Press the MENU BUTTON on the Model 541 after you turn the unit on to access the configuration mode. Turn the EZ-Dial™ Knob to select configuration items. Press the EZ-Dial™ Knob to change configuration items. Then press the Menu or STORE/CLEAR button to save selections and to exit.

→ AUTO OFF	ON
X1/X10	X10
0 XING/BASED	XING
EZ-CHECK	ON
SINE/SQ	SQ
<b>BASIC CONFIGURATION</b>	

### Auto Off - ON (default)/OFF

Auto Off is ON, by default, to save battery life by turning the unit off after 30 minutes of inactivity. Turn Auto Off to OFF to prevent automatic shutdown. This is typically useful for manual loading or continuous use.

### X1/X10 - X1 (default)

This selection is for attenuation of input signals factored by X1 or by X10, X1 for voltage between 1 - 12Vpk or X10 for voltages between 1 - 120Vp.

### 0 XING/BASED Based (default)

This selection gives the users the ability to change output signals between Zero Based and Zero Crossing. This gives the user the ability to select 0 XING for Zero Crossing Square or Sine waves to be able to output signals that go from positive to negative. Zero Based Square Wave to output only positive signals.

**NOTE: FOR SIMULATING NEGATIVE ONLY SIGNALS, SWAP THE BLACK AND RED LEAD WIRES IN ZERO BASED MODE.**

### EZ-Check™ HI/LO Readings ON (default)

If the EZ-Check™ HI/LO Readings option is ON, the highest and lowest readings will automatically be saved in the HI and LO EZ-Check™ positions.

If this option is OFF the HI and LO positions will show the current reading.

### SINE/SQ SQ (default)

This selection gives the users two choices to choose from for an output signal:  
Sign Wave Signal or Square Wave Signal

## BASIC CONFIGURATION

If Basic Configuration is selected, the unit will restore all factory defaults. This will reset any changes made in the Model 541 Configuration options, returning the unit to its simplest factory configuration. Which means Auto Off is on, range at x1, Zero Based Square Wave, EZ-Check is on and Square wave is selected.





## Model 541 Operating Instructions

### C. EZ-Dial™ Knob

Source mode - Adjust the output up and down with the EZ-Dial™ knob. The increment is the far right digit (XXXX1). Press while turning to adjust 100X faster (XX1XX)

Read mode - Trigger level adjustment. Adjust knob until LED Blinks and Reading is displayed.

### D. EZ-Check™ Switch

The EZ-Check™ switch has three positions -- high, set, and low. Its position is shown at the left edge of the LCD display with "HI" and "LO" indicators. Use of the EZ-Check™ switch depends on mode:

#### Source Modes:

Slide the EZ-Check™ switch to the HI and LO positions to recall the settings stored in those positions. While in the HI and LO positions, dial the EZ-Dial™ knob to change the display. Press **STORE/CLEAR** to save new settings in the HI and LO positions. The display will flash "STORED" to confirm.

*Hint: For faster calibrations, the position of the switch can be felt. This feature allows continuous monitoring of the device being calibrated without looking back at the Model 541 display. This is also useful in poor lighting or under difficult operating conditions.*

#### Read Modes:

In read modes, with the EZ-Check™ switch in the middle position, the Model 541 calibrator records the maximum and minimum readings observed in each mode. Slide the EZ-Check™ switch to the HI and LO positions to display the readings. Press **STORE/CLEAR** to clear the readings. The display will flash "CLEARED" to confirm.

### E. TOTALIZE Pushbutton

The EZ-Step™ Switch pushbutton is a feature for read and source modes.

Push the EZ-Step™ like a stop watch to run or stop Totalizing.


### F. FREQUENCY OUTPUT (SOURCE MODE)

Press the SOURCE button to select the Frequency output mode, the word Source will appear on the LCD Display. Press the SOURCE button to select the desired frequency range. Press and hold the Source/Amplitude button to enter the Amplitude adjustment screen. Then turn the EZ-Dial™ knob to select the desired Level (amplitude) this will be indicated on the LCD. Levels are indicated in Vp and Vpp with respect to the black lead (-). Then press the SOURCE/AMPLITUDE or STORE/CLEAR button to save selections and to exit.

You are able to setup three desired set points for quick calibration. Use the **EZ-Check™** slide switch. Slide the EZ-Check™ switch to the HI and dial the EZ-Dial™ to the desired set point. Press the STORE/CLEAR button to save settings. Do the same in the LO positions. For the mid range just dial it to the set point. It will stay at that point unless you move the EZ-Dial™. This is so you may test linearity in the mid range while maintaining the 0% and 100% end points.

Connect the Model 541 to the output of the equipment or sensor to being calibrated then slide the EZ-Check™ switch to the HI, MIDDLE and LO positions to recall the settings stored in those positions.

If you need to change set points, while in the HI and LO positions, dial the EZ-Dial™ knob to change the display. Press **STORE/CLEAR** to save new settings in the HI and LO positions. The display will flash "STORED" to confirm.





## Model 541 Operating Instructions

### G. FREQUENCY COUNTER (READ MODE)

Press the READ button to select the READ mode, the word READ will appear on the LCD Display. Press the READ button to select the desired frequency range. Press the Menu button and select the Level (amplitude) X1 for signals 0.1 to 12Vp or X10 for signals from 1 to 120Vp. Then press the READ/GATE TIME or STORE/CLEAR button to save selections and to exit.

In read modes, the Model 541 calibrator records the maximum and minimum readings observed in each mode. Connect the Model 541 to the equipment or sensor being measured and use the **EZ-Check™** slide switch in the center position to monitor the frequency. Slide the EZ-Check™ switch to the HI and LO positions to display the min. & max. readings. Press **STORE/CLEAR** to clear the readings. The display will flash "CLEARED" to confirm.

### H. FUNCTION OF THE GREEN LED

The Model 541 is equipped with a GREEN LED light. It is being used in the Read mode to let the user know that their signal is being detected by the calibrator when the LED is flashing. If the LED is not lit, the user must adjust the trigger level. NOTE: Led will appear solid above Frequency of 60Hz.

### I. TOTALIZE (READ MODE)

The Model 541 will count pulses with-in the users defined period. Press the Menu button and select the Level (amplitude) X1 for signals 0.1 - 12Vp or X10 for signals from 1V to 140Vp. Then press the Menu or STORE/CLEAR button to save selections and to exit. Press the READ/GATE TIME button and select the TOTALIZER mode. Press and hold the READ/GATE TIME button and adjust the number of minutes (1-100) that you want the Model 541 to count pulses. Then press the READ/GATE TIME or STORE/CLEAR button to save selections and to exit. Then turn the EZ-Dial™ knob to adjust the trigger time. This will be indicated on the LCD.

Connect the Model 541 to the output of the equipment or sensor being measured and push the EZ-Step™ push button on the side of the unit, similar to a Stop Watch, to run or stop Totalizing. The words RUN or STOP will appear on the LCD display.

**See Totalizer Connections on next page.**

### J. CALIBRATE TOTALIZERS (SOURCE MODE)

The Model 541 will count pulses with-in a selected time frame. Press the SOURCE/AMPLITUDE button and select the TOTALIZER mode. Press and hold the READ/GATE TIME button and adjust the number of minutes (1-100) that you want the Model 541 to output pulses. Then press the SOURCE/AMPLITUDE or STORE/CLEAR button to save selections and to exit. Then turn the EZ-Dial™ knob to adjust the number of pulses required during the time period defined. This will be indicated on the LCD.

Connect the Model 541 to the output of the equipment or sensor to be calibrated then Press the Slide the EZ-Check™ Switch to start.

**See Calibrate Totalizers Connection diagram on next page.**







# Model 541 Operating Instructions

## TOTALIZE CONNECTIONS

Connect the Model 541 to the output of the equipment or sensor to be measured and push the EZ-Step™ pushbutton like a stop watch to run or stop Totalizing. The words RUN or STOP will appear on the LCD display.



## CALIBRATE TOTALIZERS



Connect the Model 541 to the input of the equipment or sensor to be calibrated. Slide the EZ-Check™ switch to the HI and LO positions to recall the settings stored in those positions.

